




120VAC 6 CIRCUIT 20AMPS MAX	3 = H CKT 2 4 = N CKT 2 5 = H CKT 3 6 = N CKT 3 7 = H CKT 4 8 = N CKT 4	9 = H CKT 5 10 = N CKT 5 11 = H CKT 6 12 = N CKT 6 13-19 = GROUND RING
PINOUT: P19-01 1 = H CKT 1 2 = N CKT 1		

208VAC 6 CIRCUIT 20AMPS MAX	3 = H CKT 2 4 = H CKT 2 5 = H CKT 3 6 = H CKT 3 7 = H CKT 4 8 = H CKT 4	9 = H CKT 5 10 = H CKT 5 11 = H CKT 6 12 = H CKT 6 13-19 = GROUND RING
PINOUT: P19-04 1 = H CKT 1 2 = H CKT 1		

